

# FSC Enabling Codes Part Sales

As July of 2014 NO OFFICIAL

Description	Application-Number (AN) (AppID)	Upgrade-Index (UI)	MEDIA-TYPE
<b>CCC -0x63-</b>			
CCC Voice Recognition Code Retrofit/Repair	0002 (AppID 2)	0001	Download from ASAP
CCC Voice Recognition Code Retrofit/Repair	0020 (AppID 32)	0001	Download from ASAP
<b>CIC -0X63-</b>			
CIC Navigation Code HB Retrofit/Repair	0019 (AppID 25)	0001	Download from ASAP
CIC Voice Recognition Code Retrofit/Repair	0017 (AppID 23)	0001	Download from ASAP
CIC Navigation Enabler Code Retrofit/Repair	001B (AppID 27)	0001	Download from ASAP
CIC Map Europe 2010	0028 (AppID 40)	0001	Download from ASAP
CIC Map Europe 2011	0028 (AppID 40)	0002	Download from ASAP
CIC Map Europe 2012	0028 (AppID 40)	0003	Download from ASAP
CIC Map Europe 2013	0028 (AppID 40)	0004	Download from ASAP
CIC Map Europe 2013-2	0028 (AppID 40)	0005	Download from ASAP
CIC Map Europe 2014	0028 (AppID 40)	0006	Download from ASAP
CIC Map Europe 2014-2	0028 (AppID 40)	0007	Download from ASAP
CIC Map Europe 2015	0028 (AppID 40)	0008	Download from ASAP
CIC Map Europe 2015-2	0028 (AppID 40)	0009	Download from ASAP
CIC Map Europe 2016	0028 (AppID 40)	0010	Download from ASAP
CIC Map Europe 2016-2	0028 (AppID 40)	0011	Download from ASAP
CIC Map North America 2010	002D (AppID 45)	0001	Download from ASAP
CIC Map North America 2010	002D (AppID 45)	0002	Download from ASAP
CIC Map North America 2011	002D (AppID 45)	0003	Download from ASAP
CIC Map North America 2012	002D (AppID 45)	0004	Download from ASAP
CIC Map North America 2013	002D (AppID 45)	0005	Download from ASAP
CIC Map North America 2013-2	002D (AppID 45)	0006	Download from ASAP
CIC Map North America 2014	002D (AppID 45)	0007	Download from ASAP
CIC Map North America 2014-2	002D (AppID 45)	0008	Download from ASAP
CIC Map North America 2015	002D (AppID 45)	0009	Download from ASAP
CIC Map North America 2015-2	002D (AppID 45)	0010	Download from ASAP
CIC Map North America 2016	002D (AppID 45)	0011	Download from ASAP
CIC Map North America 2016-2	002D (AppID 45)	0012	Download from ASAP
CI63F1	0030 (AppID 48)	0001	Download from ASAP
CIC SDARS Code Retrofit/Repair	006F (AppID 111)	0001	Download from ASAP
CIC BMW Apps Enabling Code	009C (AppID 156)	0001	Download from ASAP
<b>CIC MID -0X63-</b>			
CIC MID Voice Recognition Code Retrofit/Repair	0044 (AppID 68)	0001	Download from ASAP
CM63F1 PL2	0045 (AppID 69)	0001	Download from ASAP
CIC MID SDARS Code Retrofit/Repair	006F (AppID 111)	0001	Download from ASAP

# FSC Enabling Codes Part Sales

As July of 2014 NO OFFICIAL

Description	Application-Number (AN) (AppID)	Upgrade-Index (UI)	MEDIA-TYPE
<b>Champ2 -0x63-</b>			
Champ2 Voice Recognition Repair Code	0024 (AppID 36)	0001	Download from ASAP
Champ2 Media Player (USB) Repair Code	0072 (AppID 114)	0001	Download from ASAP
Champ2 BMW Apps Enabling Code	008E (AppID 142)	0001	Download from ASAP
Champ2 Voice Recognition Repair Code Asia	0027 (AppID 39)	0001	Download from ASAP
Champ2 NAV IBOC SDARS1 (US)	0071 (AppID 113)	0001	Download from ASAP
<b>NBT -0x63-</b>			
Navigation Code HB Retrofit/Repair	00A0 (AppID 160)	0001	Download from ASAP
Navigation Enabler Code Retrofit/Repair	00DE (AppID 222)	0001	Download from ASAP
Voice Recognition Code Retrofit/Repair	009E (AppID 158)	0001	Download from ASAP
Lab Timer (M-Vehicles only)	00E5 (AppID 229)	0001	Download from ASAP
Map Europe 2012	00A9 (AppID 169)	0001	Download from ASAP
Map Europe 2013	00A9 (AppID 169)	0002	Download from ASAP
Map Europe 2013-2	00A9 (AppID 169)	0003	Download from ASAP
Map Europe 2014	00A9 (AppID 169)	0004	Download from ASAP
Map Europe 2014-2	00A9 (AppID 169)	0005	Download from ASAP
Map Europe 2015	00A9 (AppID 169)	0006	Download from ASAP
Map Europe 2015-2	00A9 (AppID 169)	0007	Download from ASAP
Map Europe 2016	00A9 (AppID 169)	0008	Download from ASAP
Map Europe 2016-2	00A9 (AppID 169)	0009	Download from ASAP
Map North America 2012	00A8 (AppID 168)	0001	Download from ASAP
Map North America 2013	00A8 (AppID 168)	0002	Download from ASAP
Map North America 2013-2	00A8 (AppID 168)	0003	Download from ASAP
Map North America 2014	00A8 (AppID 168)	0004	Download from ASAP
Map North America 2014-2	00A8 (AppID 168)	0005	Download from ASAP
Map North America 2015	00A8 (AppID 168)	0006	Download from ASAP
Map North America 2015-2	00A8 (AppID 168)	0007	Download from ASAP
Map North America 2016	00A8 (AppID 168)	0008	Download from ASAP
Map North America 2016-2	00A8 (AppID 168)	0009	Download from ASAP
CIC SDARS Code Retrofit/Repair	006F (AppID 111)	0001	Download from ASAP
CIC BMW Apps Enabling Code	009C (AppID 156)	0001	Download from ASAP
TextToSpeech	009F (AppID 159)	0001	Download from ASAP
<b>Entry Radio Headunit -0x63-</b>			
Entry SDARS Retrofit/Repair	006F (AppID 111)	0001	Download from ASAP
Entry Media Player Retrofit/Repair	0081 (AppID 129)	0001	Download from ASAP
Entry Telephone Retrofit/Repair	0082 (AppID 130)	0001	Download from ASAP
Entry Voice Recognition Retrofit/Repair	008F (AppID 143)	0001	Download from ASAP
Entry Online Browser Retrofit/Repair	0090 (AppID 144)	0001	Download from ASAP

# FSC Enabling Codes Part Sales

As July of 2014 NO OFFICIAL

Description	Application-Number (AN) (AppID)	Upgrade-Index (UI)	MEDIA-TYPE
<b>RADIO2 -0x63-</b>			
Radio2 SDARS Retrofit/Repair	0078 (AppID 120)	0001	Download from ASAP
Radio2 Bluetooth telephone Retrofit/Repair	007C (AppID 124)	0001	Download from ASAP
Radio2 Audio player Ipod Retrofit/Repair	007D (AppID 125)	0001	Download from ASAP
<b>SPECIAL Navigations System -0x63-</b>			
NIVI_ab_09_05	0004 (AppID 4)	0001	Download from ASAP
NIVI65	0005 (AppID 5)	0001	Download from ASAP
NAVI_CE2_ab_03_05 (JAPON)	0008 (AppID 8)	0001	Download from ASAP
<b>Navigation MINI COOPER -0x63-</b>			
CH63PKR ECE USB BT 2LG	009B (AppID 155)	0001	Download from ASAP
CH63PKR US NAV USB BT IBOC_SDR	0046 (AppID 70)	0001	Download from ASAP
<b>EPS -0x30-</b>			
Servotronic Retrofit Code (EPS) for F25	0083 (AppID 131)	0001	Download from ASAP
Servotronic Retrofit Code (EPS) for E8x and E9x	0084 (AppID 132)	0001	Download from ASAP
<b>BMW Tuning -0x12-</b>			
Power Kit Enabling Code (MED172 / P141US)	001C (AppID 28)	0001	Download ASAP
Power Kit Enabling Code (MED172) ECE MT Spec	001F (AppID 31)	0001	Download ASAP
Power Kit Enabling Code S54 (MSS70)	0013 (AppID 19)	0001	Download ASAP
Power Kit Enabling Code S65 (MSS60)	0016 (AppID 22)	0001	Download ASAP
Power Kit Enabling Code N54 (MSD81 / MSD80)	007A (AppID 122)	0001	Envelope/Download ASAP
Power Kit Enabling Code S63 (MSD851)	0070 (AppID 112)	0001	Download ASAP
Power Kit Enabling Code N63 (MSD851)	0085 (AppID 133)	0001	Envelope/Download ASAP
Power Kit Enabling Code N55	0086 (AppID 134)	0001	Envelope/Download ASAP
Power Kit Enabling Code N54 (MSD81)	0093 (AppID 147)	0001	Download ASAP
Power Kit Enabling Code N54 (MSD81)	0096 (AppID 150)	0001	Download ASAP
Power Kit M M5 S63B44 (tü) (MEVD1728)	0097 (AppID 151)	0001	Download ASAP
Power Kit M M5 S63B44 (tü) (MEVD1728)	0098 (AppID 152)	0001	Download ASAP
<b>MINI COUPER Tuning -0x12-</b>			
Power Kit Tuning Code (N18B16) MT-FWD	00E3 (AppID 227)	0001	Download ASAP
Power Kit Tuning Code Q154 (N18) AT-FWD-JCW-JPN	00C6 (AppID 198)	0001	Download ASAP
Power kit Tuning Code (N18B16) John Works AT-FWD	0077 (AppID 119)	0001	Download ASAP
Power Kit Tuning Code (N16B14) EU (MEV1722)	0075 (AppID 117)	0001	Download ASAP

# FSC Enabling Codes Part Sales

As July of 2014 NO OFFICIAL

Description	Application-Number (AN) (AppID)	Upgrade-Index (UI)	MEDIA-TYPE
<b>BMW MOTOCICLETE Tuning -0x12-</b>			
BMSKP 6 K46 (Japan)	001E (AppID 30)	0001	Download ASAP
BMSKP 2 K44 TÜ SF	0014 (AppID 20)	0001	Download ASAP
BMSKP 7 K72 MUE / K75 (US)	00E2 (AppID 226)	0001	Download ASAP
BMSKP 6 03 K46MUE (Japan)	0092 (AppID 146)	0001	Download ASAP
BMSKP 6 06 K46 MUE RACE POWER	0094 (AppID 148)	0001	Download ASAP
BMSKP 6 05 K42 (Taiwan)	00E0 (AppID 224)	0001	Download ASAP
BMSKP 6 11 K46 ECE 79KW TITAN HO	00A2 (AppID 162)	0001	Download ASAP
<b>DSC Mini Cooper -0x29-</b>			
DSC56 2IB	0025 (AppID 37)	0001	Download ASAP
<b>NVC / NIVI -0x57-</b>			
Night Vision Control Unit Enabling Code	0004 (AppID 4)	0001	CD supplied with Kit
Night Vision Camera Enabling Code	0005 (AppID 5)	0001	CD supplied with Kit
<b>KAFAS -0x93-</b>			
Speed Limit "SLI" Retrofit / Repair Code	007E (AppID 126)	0001	Download from ASAP
Front Collision Warning Retrofit / Repair Code	00BE (AppID 190)	0001	Download from ASAP
Pedestrian Detection Retrofit / Repair Code	00BF (AppID 191)	0001	Download from ASAP
<b>Especial for ASIA -0x3B- / -0x63-</b>			
NAVI_ CE2_ab_03_05 (JAPON)	0008 (AppID 8)	0001	Download from ASAP
CI63F1 Navigation Enabling Code (Japan)	001B (AppID 27)	0001	Download ASAP
Japan_Nav_CE3_RR	001D (AppID 29)	0001	Download from ASAP
BMSKP 6 K46 (Japan)	001E (AppID 30)	0001	Download ASAP
NAVI JAP	0010 (AppID 16)	0001	Download ASAP
CI63F1 Navigation Application (Japan)	0019 (AppID 25)	0001	Download ASAP
CI63F1 Navigation Voice (Japan)	0017 (AppID 23)	0001	Download ASAP
Navigation Application Code (Asia-Japan)	0027 (AppID 39)	0001	Download from ASAP
Voice Recognition Repair Code (Asia)	0043 (AppID 67)	0001	Download from ASAP
Q85-N16M0-MKS-AT-LL-FWD-(China)	0076 (AppID 118)	0001	Download from ASAP
BMSKP 6 K46 MUE (Japan)	0092 (AppID 146)	0001	Download ASAP
BMSKP 6 05 K42 (Taiwan)	00E0 (AppID 14)	0001	Download ASAP